

Overlap here needs to be trimmed. The flybridge will be removed before transport and reinstalled upon arrival in Alaska. Make sure the sealer is on the BOM and BOL and that it ships with the boat.

**SEAGLAZE™** Window to be installed here after completion of weldout  
(per Seaglaze Spec 013ABS014)

If the frames do not show intersecting lines then the deck sheet has not been notched. This area will need to be evaluated closer.